

Tel No.: (053) 255-8683

c/o Vanilyn C. Catampatan/ Ray Debhosaur E. Porcadilla

Republic of the Philippines DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS LEYTE 4TH DISTRICT ENGINEERING OFFICE



Ormoc City, Region VⅢ 2024-06-133 Request for Quotation (P. R. No.): DPWH 4TH DEO Name of Procuring Entity: Date June 11, 2024 Revised on : REQUEST FOR QUOTATION Standard Form/Title: Office/End-User: COMPANY NAME: VICTOR S. SUPLICO, III ADDRESS : TEL. NO. / FAX NO. : TERMS AND CONDITIONS : 1. All entries must be typewritten or legibly written. 2. All pages must be duly signed. 3. Delivery period within 20 C. D. upon receipt of the approved funded Purchase Order (P. O.). Administrative penalties pursuant to Sec. 69 of the Revised IRR-RA 9184 shall be for a minimum for non-delivery without valid reason. 4. Warranty shall be for a minimum of three (3) months for supplies & materials: one year for Equipment fron date of PETER S acceptance by the end-user.

5. Price validity shall be for a period of sixty (60) calendar days.

G-EPS Registration Number & Mayor's Permit/Business Permit & Omnibus shall be attached upon submission of the quotation. 7. Bidders shall submit original brochures showing certifications of the product if applicable. 8. Quotations to be submitted by Lot 9. Please indicate the brand for each item being offered. 10. Fco -friendly supplies/equipment P112,400.00 11. The approved budget ceiling for this procurement is 12. Quotations submitted thru mail & Fax will not be accepted. UNIT PRICE TOTAL PRICE OTY. UNTE ITEM / DESCRIPTION Item No. Repair and Replacement of damaged parts Steering system of Service Vehicle TOYOTA HILUX: Plate No. GAM-2188 BOE No.H1-8445: Prop No: 1060601000-C12MV002-2020-06-01101101-2019 (2hrs) Replace Rack End LH (1pc) End S/A, Steering Rack (2hrs) Replace Rack End RH (1pc) End S/A, Steering Rack (0.5hrs)Replace Brake Light Bulb (1pc) Bulb 12V, 21W5W (4.033hrs)Perform Complete Wheel Alignment Geniune parts compatible to TOYOTA HILUXNOTHING FOLLOWS..... Repair and Replacement of damaged parts of brake system of Service Vehicle TOYOTA HILUX: Plate No. YU-8416 BOE No.H1-8446 Prop No: 1060601000-C12MV002-2016-12-01101101-0405 (3hrs) Replace Rotor Disc RH LH (2pcs) Disc, FR (2pcs) Brake Stop Squel kit (5pcs) Rags GJ Geniune parts compatible to TOYOTA HILUX Repair and Replacement of damaged parts of transmission system of Service Vehicle TOYOTA HILUX: Plate No. YU-8416 BOE No.H1-8446: Prop No: 1060601000-C12MV002-2016-12-01101101-0405 (13hrs) Pull Down Transmission Replace Lining (1pc) Bearing, Radial Ball (1assy) Disc Assy, Clutch (1assy) Cover Assy, Clutch (1assy) Bearing Assy, Clutch Release (2pcs) Brake Cleaner (15pcs) Rags GJ (1pc) Toyota Genuine Bactaklenz (7ml) (4hrs) Replace Brake Pad Brake Shoe (1set) Pad kit, Disc Brake Shoe kit (1pc) Toyota Genuine Engine Room Coat (1pc) (1hr) Toyota Car Care (1pc) Toyota Genuine Engine Room Coat Cleaner (3.3 hrs) Replace Rack End RH LH (2pcs) End S/A, Steering Rack Geniune parts compatible to TOYOTA HILUXNOTHING FOLLOWS FOR THE PROCUREMENT OF REPAIR AND REPLACEMENT OF DAMAGED PARTS FOR PLATE NO. GAM-2188 and YU-8416 @DPWH LEYTE 4TH DEO Warranty Brand and Model Price Validity After having carefully read and accepted your General Conditions, I / We quote you on the item(s) at price note above. If the space for Delivery Period, Warranty and Price Validity/ are left blank, it means that I concur with the Terms and Conditions specified by DPWH.

> Website: www.dpwh.gov.ph Tel. No(s).: 561-8012 / 255-2230



Printed Name / Signature / Date

Tel. No. / Cellphone No. / E.mail Address

150 9001