

15	System Reprocess, Recharging of Freon, Leak Test and Vacuum	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	6,550.00	0.00	
	Breaker Replacement	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	550.00	0.00	
	Replacement of Compressor Unit	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	5,050.00	0.00	
	Cleaning	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	1,150.00	0.00	
	Extension of Copper Pipes, Rubber Insulations, Communication Wires and Etc.	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	7,050.00	0.00	
	Compressor	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	27,500.00	0.00	
	Magnetic Contactor	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	750.00	0.00	
	FCU and ACCU units FINANCE (S/Nos: BK293184, BK293203, BK293199 & BK293205)																									0.00				
	Capacitor	unit	0	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	1,350.00	0.00
	Home/Well	unit	0	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	1,350.00	0.00
	Molding	length	0	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	150.00	0.00
	16	System Reprocess, Recharging of Freon, Leak Test and Vacuum	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	6,550.00	0.00
Breaker Replacement		unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	550.00	0.00	
Replacement of Compressor Unit		unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	5,050.00	0.00	
Cleaning		unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	1,150.00	0.00	
Extension of Copper Pipes, Rubber Insulations, Communication Wires and Etc.		unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	7,050.00	0.00	
Compressor		unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	27,500.00	0.00	
Magnetic Contactor		unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	750.00	0.00	
FCU and ACCU units (Planning Section) - (S/Nos: BK293191, BK293188, BK293197 & BK293186, 4M1322501 - RROW & 1 UNIT Ceiling Mounted Airconditioner 3 tons - (DAIKIN) - Survey team)																									0.00					
Capacitor		unit	0	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	1,350.00	0.00
Home/Well		unit	0	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	1,350.00	0.00
Molding		length	0	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	150.00	0.00
17		System Reprocess, Recharging of Freon, Leak Test and Vacuum	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	6,550.00	0.00
	Breaker Replacement	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	550.00	0.00	
	Replacement of Compressor Unit	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	5,050.00	0.00	
	Cleaning	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	1,150.00	0.00	
	Extension of Copper Pipes, Rubber Insulations, Communication Wires and Etc.	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	7,050.00	0.00	
	Compressor	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	27,500.00	0.00	
	Magnetic Contactor	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	750.00	0.00	
	FCU and ACCU units (A.D.E. Office) - (S/Nos: EJS00959 & EJS00966)																									0.00				
	Capacitor	unit	0	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	1,350.00	0.00
	Home/Well	unit	0	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	1,350.00	0.00
	Molding	length	0	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	150.00	0.00
	18	System Reprocess, Recharging of Freon, Leak Test and Vacuum	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	6,550.00	0.00
Breaker Replacement		unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	550.00	0.00	
Replacement of Compressor Unit		unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	5,050.00	0.00	
Cleaning		unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	1,150.00	0.00	
Extension of Copper Pipes, Rubber Insulations, Communication Wires and Etc.		unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	7,050.00	0.00	
Compressor		unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	27,500.00	0.00	
Magnetic Contactor		unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	750.00	0.00	
FCU and ACCU units (Maintenance Section) - (S/Nos: AK293289, BK293196 & BK293194)																									0.00					
Capacitor		unit	0	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	1,350.00	0.00
Home/Well		unit	0	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	1,350.00	0.00
Molding		length	0	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	150.00	0.00
		System Reprocess, Recharging of Freon, Leak Test and Vacuum	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	6,550.00	0.00
	Breaker Replacement	unit	0	0	0	0	0	0.00	0	0	0	0	0	0.00	0	0	0	0	0.00	0	0	0	0	0	0	0.00	0	550.00	0.00	
	Replacement of Compressor Unit	unit	0	0	0	0	0	0.00	0																					

