

Department of Public Works and Highways

Contract ID : 25BF0101
 Contract Name : Repair/Maintenance of DPWH Buildings and other Related Activities
 1. Repair/Maintenance of DPWH Building Isabela 2nd District Engineering Office, Employees Quarters (Supply Office) Roxas, Isabela
 2. Repair/Rehabilitation of DPWH Building Isabela 2nd District Engineering Office, Motorpool II, Roxas, Isabela
 Location of the Contract : Roxas, Isabela



REPUBLIC OF THE PHILIPPINES
 DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS
ISABELA 2ND DISTRICT ENGINEERING OFFICE

ROXAS, ISABELA



BID BULLETIN-0101-1

TO : ALL PROSPECTIVE BIDDERS
BAC MEMBERS
TWG MEMBERS
OTHERS CONCERNED

DATE : July 21, 2025

Please take notice for the **Change of, Quantities** as a result of thorough checking by the Maintenance Section, this Office, for the above-stated proposed contract. Hence the new Quantities of the project should be adopted in all Bidding Documents and other procurement/contract forms, to wit:

Contract ID: **25BF0101**

Quantities:

1. Repair/Maintenance of DPWH Building Isabela 2nd District Engineering Office, Employees Quarters (Supply Office) Roxas, Isabela

| Item No. | Description | Unit | Old Quantity | New Quantity | Remarks |
|-----------------|--|----------------|--------------|--------------|----------------|
| Part I | FACILITIES FOR THE ENGINEER | | | | |
| A.1.4(1) | Provision of Progress Photographs | mo | 3.33 | 3.33 | SAME |
| Part II | OTHER GENERAL REQUIREMENTS | | | | |
| B.5(1) | Project Billboard / Signboard | ea | 2.00 | 2.00 | DELETED |
| B.7 (1) | Occupational Safety and Health | l.s. | 1.00 | 1.00 | SAME |
| B.9(1) | Mobilization / Demobilization | l.s. | 1.00 | 1.00 | DELETED |
| B.24(1) | General scaffolding | l.s. | 1.00 | 1.00 | SAME |
| PART III | CIVIL, MECHANICAL, ELECTRICAL AND SANITARY/PLUMBING WORKS | | | | |
| PART C | EARTHWORKS | | | | |
| 801(1) | Removal of Structures and Obstruction | l.s. | 1.00 | 1.00 | SAME |
| 803(1)a | Structure Excavation (Common Soil) | m ³ | 1.50 | 1.50 | SAME |
| PART B | PLAIN AND REINFORCED CONCRETE WORKS | | | | |

Department of Public Works and Highways

Contract ID : 25BF0101

Contract Name : Repair/Maintenance of DPWH Buildings and other Related Activities

1. Repair/Maintenance of DPWH Building Isabela 2nd District Engineering Office, Employees Quarters (Supply Office) Roxas, Isabela
2. Repair/Rehabilitation of DPWH Building Isabela 2nd District Engineering Office, Motorpool II, Roxas, Isabela

Location of the Contract : Roxas, Isabela

| | | | | | |
|---------------|--|----------------|----------|---------|------------------|
| 900(1)c | Structural Concrete, 3000 psi, Class A, 28 days | m ³ | 4.65 | 4.65 | SAME |
| 902(1)a1 | Reinforcing Steel (Deformed), Grade 40 | kg | 48.06 | 48.06 | SAME |
| PART C | FINISHING | | | | |
| 1003(1)a1 | Ceiling, 4.5 mm, Metal Frame, Fiber Cement Board | m ² | 21.00 | 21.00 | SAME |
| 1008(2) | Aluminum Glass Window (Awning/Sliding/Fixed) | l.s. | 1.00 | 1.00 | SAME |
| 1010(1) | Frames (Jambs, Sill, Head, Transoms and Mullions) | set | 1.00 | 1.00 | SAME |
| 1010(2)b | Doors (Wood Panel) | m ² | 1.68 | 1.68 | SAME |
| 1011(2) | Roll-Up Doors | l.s. | 1.00 | 1.00 | |
| 1014(1)b1 | Pre-painted Metal Sheets above 0.427 mm, Corrugated, Long Span | m ² | 9.28 | 9.28 | SAME |
| 1018(1) | Glazed Tiles and Trims | m ² | 21.00 | 21.00 | SAME |
| 1032(1)a | Painting Works, Masonry/Concrete | m ² | 1,463.97 | 1463.97 | SAME |
| 1032(1)b | Painting Works, Wood | m ² | 393.37 | 429.95 | INCREASED |
| 1032(1)c | Painting Works, Steel | m ² | 526.28 | 526.28 | SAME |
| 1046(2)a1 | CHB Non-Load-Bearing (Including Reinforcing Steel), 100 mm | m ² | 40.00 | 40.00 | SAME |
| 1047(4)a | Metal Structure Accessories, Bolts and Rods | pc | 20.00 | 20.00 | SAME |
| 1047(5)d | Metal Structure Accessories, Steel Plates | kg | 32.00 | 32.00 | SAME |
| 1047(8)a | Structural Steel, Trusses | kg | 143.00 | 143.00 | SAME |
| 1047(8)b | Structural Steel, Purlins | kg | 24.00 | 80.00 | INCREASED |

Please be guided accordingly.

ROLLY M. CABAUATAN
Chief, Quality Assurance Section
BAC Chairperson

Noted By:

JOSE B. TOBIAS, CESE
District Engineer