

Name of Procuring Entity

Republic of the Philippines

DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS

SOUTH COTABATO 1ST DISTRICT ENGINEERING OFFICE

REGIONAL OFFICE XII

Tindalo St., Balite, Brgy. Lagao, General Santos City

	-			
Revised on:	Date: April 3, 2024			
Standard Form/Title : REQUEST FOR QUOTATION (Small Value Procurement)	Office/End - User :	Maintenance Section		
COMPANY NAME :				
ADDRESS :				

TEL. NO./FAX No. : TIN:

Please quote your lowest price on the item(s) listed below. Subject to the Terms and Conditions stated below and submit your quotation duly signed by your representative not later than 10:00 A.M. Of April 8, 2024 in the return envelope attached herewith to Procurement Office of Department

of Public Works and Highways South Cotabato 1st District Engineering Office, Tindalo St., Balite, Brgy. Lagao, General Santos City.

: DPWH So. Cot. 1ST , DEO, GSC

TERMS and CONDITIONS:

- 1. All entries must be typewritter or legibly written.
- 2. Delivery period within 60 CD upon receipt of the approved funded Purchase

Order (P.O), Administrative penalties pursuant to Sec. 69 of the Revised IRR-RA

9184 shall be imposed for non-delivery without valid reason.

3. Warranty shall be for a minimum of three (3) months for supplies & materials; one year for Equipment; 3 years IT Equipment from date of acceptance by the end-user.

- 4. Price validity shall be for a period of sixty (60) calendar days.
- 5. G-EPS Registration Number/Mayor's Permit/DTI & Omnibus Sworn Statement

shall be attached upon submission of the quotation

- 6. Bidders shall submit original brochures of the product.
- 7. Please indicate the brand for each items being offered.
- 8. The approved budget ceiling for this procurement is per lot.

TEODY R. GALANG
Chief, Construction Section
BACChairperson

2024-04-0 -027

Request for Quotation PR No:

Item No.	ITEMS & DESCRIPTION	ABC	QTY	UNIT	UNIT PRICE	TOTAL PRICE
	Supply and Delivery of (Lot A - Materials) and (Lot B - Pakyaw Labor) for Work CAT 10 Act 41X Emergency Project -Repair of Damaged PCCP with Center Island alongMakar-iamba Road (S00246MN) K1661+280-K1661+327 and Albert Morrow Blvd. (Western Section (S00729MN), K1661+278-K1661+281).					
	LOT A: Materials for Work CAT 10 Act 41X Emergency Project -Repair of Damaged PCCP with Center Island alongMakar-iamba Road (S00246MN) K1661+280- K1661+327 and Albert Morrow Blvd. (Western Section (S00729MN), K1661+278-K1661+281)	560,148.40				
1	Aggregate -Subbase Course		43.57	cu.m.		
2	Reinforcing Steel Bar		578.23	kg		
3	Curing Compound		54.94	L		
4	Asphalt Sealant		32.21	L		
5	Steel Forms (Rental)		87.15	m		
6	Ready Mix Concrete, 3500 ps (7 days Concrete Curing)		53.05	cu.m.		
7	Concrete Saw (Diamond Bladde: 14"φ)		0.03	рс		
8	Pipe Sweet, 2"φ		1.47	m		
9	Grease/Tar		1.47	L		
10	Tie Wire #16		9.21	kg		

			1		Ī	1	
11	Coco Lumber		691.40	bd.ft.			
12	Assorted CVN (1KG/100 bd. Ft of lumber)		15.07	kgs			
13	Plywood (1/2" x 4'x8")		6.59	рс			
14	Cement		91.00	bag			
15	Sand		4.81	cu.m.			
16	Gravel 3/4		9.62	cu.m.			
17	Grave Bedding		2.95	cu.m.			
18	Concrete Neutralizer		3.70	gal			
19	Concrete Sealer/Primer		7.39	gal			
20	Patching Compound		9.241	gal			
21	Semi Gloss Latex (Two coating)		14.79	gal			
22	Traffic Instruction Signs (450mmx750mm), R3-15P		4.00	рс			
23	3" φ GI Pipe		12.40	рс			
24	Nuts and Bolts, 10mm φ x 100mm		8.00	рс			
25	Oxy/Acetylene		0.984	set			
Tota	I Amount in Figures Php:		-	-		-	
	Total Amount in Words:						
Tota	i Amount in Words:						
Tota	LOT B: Pakyaw Labor Work CAT 10 Act 41X Emergency Project -Repair of Damaged PCCP with Center Island alongMakar-iamba Road (S00246MN) K1661+280-K1661+327 and Albert Morrow Blvd. (Western Section (S00729MN), K1661+278-K1661+281)	259,851.60					
	LOT B: Pakyaw Labor Work CAT 10 Act 41X Emergency Project -Repair of Damaged PCCP with Center Island alongMakar-iamba Road (S00246MN) K1661+280-K1661+327 and Albert Morrow Blvd. (Western Section (S00729MN), K1661+278-K1661+281)		9.84	cu.m.			
	LOT B: Pakyaw Labor Work CAT 10 Act 41X Emergency Project -Repair of Damaged PCCP with Center Island alongMakar-iamba Road (S00246MN) K1661+280-K1661+327 and Albert Morrow Blvd. (Western Section (S00729MN), K1661+278-K1661+281)		9.84 115.79	cu.m.			
26	LOT B: Pakyaw Labor Work CAT 10 Act 41X Emergency Project -Repair of Damaged PCCP with Center Island alongMakar-iamba Road (S00246MN) K1661+280-K1661+327 and Albert Morrow Blvd. (Western Section (S00729MN), K1661+278-K1661+281) Removal of Structures and Obstruction, (Concrete						
26 27	LOT B: Pakyaw Labor Work CAT 10 Act 41X Emergency Project -Repair of Damaged PCCP with Center Island alongMakar-iamba Road (S00246MN) K1661+280-K1661+327 and Albert Morrow Blvd. (Western Section (S00729MN), K1661+278-K1661+281) Removal of Structures and Obstruction, (Concrete Structure Excavation (Common Soil)		115.79	cu.m.			
26 27 28	LOT B: Pakyaw Labor Work CAT 10 Act 41X Emergency Project -Repair of Damaged PCCP with Center Island alongMakar-iamba Road (S00246MN) K1661+280-K1661+327 and Albert Morrow Blvd. (Western Section (S00729MN), K1661+278-K1661+281) Removal of Structures and Obstruction, (Concrete Structure Excavation (Common Soil) Embankment from Roadway Excavation (Common Soil Subgrade Preparation (Common Material) Aggregate Subbase Course		115.79 20.8069	cu.m.			
26 27 28 29	LOT B: Pakyaw Labor Work CAT 10 Act 41X Emergency Project -Repair of Damaged PCCP with Center Island alongMakar-iamba Road (S00246MN) K1661+280-K1661+327 and Albert Morrow Blvd. (Western Section (S00729MN), K1661+278-K1661+281) Removal of Structures and Obstruction, (Concrete Structure Excavation (Common Soil) Embankment from Roadway Excavation (Common Soil Subgrade Preparation (Common Material)		115.79 20.8069 189.45	cu.m. cu.m. sq.m.			
26 27 28 29 30	LOT B: Pakyaw Labor Work CAT 10 Act 41X Emergency Project -Repair of Damaged PCCP with Center Island alongMakar-iamba Road (S00246MN) K1661+280-K1661+327 and Albert Morrow Blvd. (Western Section (S00729MN), K1661+278-K1661+281) Removal of Structures and Obstruction, (Concrete Structure Excavation (Common Soil) Embankment from Roadway Excavation (Common Soil Subgrade Preparation (Common Material) Aggregate Subbase Course Portland Cement Concrete Pavement (Unreinforced, 0.2m		115.79 20.8069 189.45 37.89	cu.m. cu.m. sq.m. cu.m.			
26 27 28 29 30 31	LOT B: Pakyaw Labor Work CAT 10 Act 41X Emergency Project -Repair of Damaged PCCP with Center Island alongMakar-iamba Road (S00246MN) K1661+280-K1661+327 and Albert Morrow Blvd. (Western Section (S00729MN), K1661+278-K1661+281) Removal of Structures and Obstruction, (Concrete Structure Excavation (Common Soil) Embankment from Roadway Excavation (Common Soil Subgrade Preparation (Common Material) Aggregate Subbase Course Portland Cement Concrete Pavement (Unreinforced, 0.2m thick, 14days)		115.79 20.8069 189.45 37.89 189.45	cu.m. cu.m. sq.m. cu.m. sq.m.			

34	Traffic Instructions Signs (450mmX750mm) R3-15P		4	each		
35	Painting Works (Masonry/Concrete)		184.82	sq.m.		
36	Grave Fill		2.81	cu.m.		
Total	Amount in Figures Php:					
Total	Amount in Words:					
The awarding for this RFQ will be on a Lot basis.			Please specify brand name otherwise, bids will not be accepted.			
Brand	and Model			•••••••		
Delive	ry Period					
Afte	er having carefully read and accepted your General Conditions, $1/$ We quote you on the	item(s) at prices				
note a	above. If the space for Delivery Period, Warranty and Price Validity are left blank, it me	ans that I concur				
with th	ne Terms and Conditions specified by DPWH.					
	c/o TEODY R. GALANG					
	BAC Chairperson		Printed Name / Signature / Date			
	DPWH, South Cotabato 1st DEO, General Santos City					
			Tel.	No. / Cellp	hone No. / E-m	ail Address

