

Republic of the Philippines DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS OFFICE OF THE SECRETARY Manila

January 27, 2017

## MEMORANDUM

FOR :

MARK A. VILLAR Secretary This Department

This refers to the memorandum dated 20 January 2017 of **DPWH Region I Assistant Director RONNEL M. TAN**, endorsing the request of District Engineer **EMIL R. GANADEN**, La Union 1<sup>st</sup> District Engineering Office for the **modification** of the hereunder stated project:

Location	Project Description		Physical Target / Cost	
	<i>as per GAA</i> UACS:165003014000156	as modified	per GAA/Original	as modified
San Fernando- Bagulin Road	MFO 1- National Road Network Services: Asset Preservation of National Roads - Preventive Maintenance based on Pavement Management System/Highway Development and	Provertive Provertive   ads - Preventive Roads - Preventive   aintenance based on Preservation of National   ads - Preventive Roads - Preventive   aintenance based on Pavement Management   ystem/Highway System/Highway   perior 27+828 Ko273+000,   porcete Reblocking - Sn Fermando-Bagulin Rd -   porcete Reblocking - Sn Ko272+828   porcete Reblocking - Sn Fermando-Bagulin Rd -   porcete Reblocking - Sn Ko273+600,   porcete Reblocking - Sn Ko273+60,   porcete Reblocking - Sn Ko273+60,   porcete Reblocking - Sn Ko273+60,   porcete Reblocking - Sn Ko277+130,   porcete Reblocking - Sn Ko277+524,   porcete Reblocking - Sn Ko277+524,   porcete Reblocking - Sn Ko277+524,   porcete Reblocking - Sn Ko277+524,	CW 1 - Preventive Maintenance of Road: Concrete Reblocking: 3.82 Lane-km	CW 1 - Preventive Maintenance of Road: Concrete Reblocking: <b>2.669 Lane-km</b> CW 2 - Const. of Slope Protection Structure: <b>744.40 Sq.m.</b>
	Management-4 (HDM-4) - Tertiary, Preventive Maintenance of Road: Concrete Reblocking - Sn Fernando-Bagulin Rd - K0272+828 - K0273+000, K0273+600 - K0275+1010, K0274+306 - K0275+003, K0277+130 - K0277 + 430,		Unit Cost: CW 1 - Preventive Maintenance of Road: Concrete Reblocking: P7,889.53/ Lane-km	Unit Cost: CW 1 - Preventive Maintenance of Road: Concrete Reblocking: PB,907.22/ Lane-km CW 2 - Const. of Slope Protection Structure: P8.5571/Sq.m.
	K0277+524 - K0277+548, K0278+000 - K0278+258 (Preventive Maintenance of Road: Concrete Reblocking)		Allocation: PhP 30.138M	Estimated Cost: PhP 30.138M

Based on our evaluation, the submitted request for modification of the said project is in order; hence, approval hereof is recommended.

EUGENIO R. PIPO, Assistant Secretary for Luzon Operations

APPROVED/DISAPPROVED:

ROMEO S. MOMO, GESO I Undersecretary Officer-In-Charge

Department of Public Works and Highways Office of the Secretary