:

January 27, 2017

MEMORANDUM

FOR

Contract of the second

ROMEO S. MOMO, CESO I

Undersecretary for Luzon Operations Officer-In-Charge

This has reference to the memorandum dated January 24, 2017 from **Asst. Reg'l. Dir. RONNEL M. TAN,** DPWH Regional Office I, relative to their request for modification for the project listed below:

LOCA	Project Description UACS No. 292003020401600		Physical Target/ Cost('000)	
	As per GAA	As modified	Original	New
Ilocos Norte	MFO 2 – Flood Management Services – Construction/ Maintenance of Flood Mitigation Structure and Drainage Systems	MFO 2 – Flood Management Services – Construction/ Maintenance of Flood Mitigation Structure and Drainage Systems –	1,755 m ²	4,631 m ²
Pagudpud. Ilc	 Installation of Slope Protection (Pagudpud, Ilocos Norte Road Slope Stabilization), Pagudpud, Ilocos Norte, K0577+770- K0578+170, K0578+197 – 	Installation of Slope Protection (Pagudpud, Ilocos Norte Road Slope Stabilization), Pagudpud, Ilocos Norte, K0577+770- K0578+170, K0578+197 –	Unit Cost ('000): P45.584/m ²	Unit Cost ('000): P17.275/m ²
2 2	K0578+360, K0578+433 - K0578+460, K0585+460 - K0585+532, K0587+060 - K0587+235, K0587+280 -	K0578+360, K0578+433 - K0578+460, K0585+460 - K0585+532, K0587+060 - K0587+235, K0587+280 -	Alloc. (`000):	Est.Cost ('000):
	K0587+360, K0587+680 – K0587+750, K0588+332 – K0588+600 [Construction of Slope Protection Structure]	K0587+360, K0587+680 – K0587+750, K0588+332 – K0588+600 [Construction of Slope Protection Structure] tion was sought due to increase in	P 80.0M	P 80.0M

Based on our evaluation, the submitted request for modification of the said project is in order; hence, approval is hereby recommended to the Honorable Secretary.

CRIPO, JR Assistant Secretary for an Operations

APPROVED/DISAPPROVED

ROMEO S. MOMO, CESO I

Undersecretary for Luzon Operations Officer-In-Charge



3.3 rbat/ERP/RSM