

Republic of the Philippines DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS NORTHERN SAMAR 2nd DISTRICT ENGINEERING OFFICE Brgy. Burabud, Laoang, Northern Samar



Name of Procuring Entity : N. Samar 2nd DEO Request for Quotation (P.R. No.) : 2025-04-0035

Revised on : Date : Standard Form/Title : REQUEST FOR QUOTATION Office/End-User : Maintenance Section

COMPANY NAME : ADDRESS :

Please quote your lowest price on the item(s) listed below, subject to the Terms and Conditions stated below and submit your quotation duly signed by your representative not later than 2:00 P.M. of <u>04 / 28 / 25</u> in the return envelope attached herewith, Procurement Unit, 2nd Floor, Brgy. Burabod, Laoang, Northern Samar.

TERMS and CONDITIONS:

TEL. NO./FAX No.

TIN

- 1. All entries must be typewritten or legibly written.
- Delivery period within 30 Days upon receipt of the approved funded Purchase Order (P.O). Administrative penalties pursuant to Sec. 69 of the Revised IRR-RA 9184 shall be imposed for non-delivery without valid reason.
- Warranty shall be for a mininum of three (3) months for supplies & materials; one year for Equipment; 3 years IT Equipment from date of acceptance by the end-user.
- 4. Price validity shall be for a period of sixty (60) calendar days.
- 5. PhilGEPS Certificate, DTI-COR, BIR-COR, Mayor's Permit, Latest BIR ITR, Tax Clearance and Omnibus Sworn Statement, shall be attached upon submission of the quotation.
- 6. Bidders shall submit original brochures of the product .
- 7. Please indicate the brand for each items being offered.
- 8. The approved budget ceiling for this procurement is

100,295.00

FRANCISCO Y. TAÑALA
Engineer III
BAC chairperson

1 Tie Rod , inner, (B2-A069, H1-6403, L300) 2 pcs 2 Tie Rod , outer, (B2-A069, H1-6403, L300) 2 pcs 3 Drag link, (B2-A069, H1-6403, L300) 1 pc 4 Ball joint, upper, (L300), (B2-A069, H1-6403, L300) 2 pcs 5 Ball joint, lower, (L300), (B2-A069, H1-6403, L300) 2 pcs 6 Idler arm, (B2-A069, H1-6403, L300) 1 pc 7 Center post, (B2-A069, H1-6403, L300) 1 pc 8 Wheel bearing, outer, (B2-A069, H1-6403, L300) 2 pcs 9 Wheel bearing, inner, (B2-A069, H1-6403, L300) 2 pcs 10 Belt trunk, (B2-A069, H1-6403, L300) 1 pc 11 Belt, (B2-A069, H1-6403, L300) 3 pcs 12 Tie Rod end, (SKA 513, H1-5103, Hilux) 2 pcs 13 Rack end, (SKA 513, H1-5103, Hilux) 2 pcs 14 Ball Joint, Upper, (SKA 513, H1-5103, Hilux) 2 pcs 15 Ball Joint, Upper, (SKA 513, H1-5103, Hilux) 2 pcs 16 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux)	
3 Drag link, (B2-A069, H1-6403, L300) 1 pc 4 Ball joint, upper, (L300), (B2-A069, H1-6403, L300) 2 pcs 5 Ball joint, lower, (L300), (B2-A069, H1-6403, L300) 2 pcs 6 Idler arm, (B2-A069, H1-6403, L300) 1 pc 7 Center post, (B2-A069, H1-6403, L300) 1 pc 8 Wheel bearing, outer, (B2-A069, H1-6403, L300) 2 pcs 9 Wheel bearing, inner, (B2-A069, H1-6403, L300) 2 pcs 10 Belt trunk, (B2-A069, H1-6403, L300) 1 pc 11 Belt, (B2-A069, H1-6403, L300) 3 pcs 12 Tie Rod end, (SKA 513, H1-5103, Hilux) 2 pcs 13 Rack end, (SKA 513, H1-5103, Hilux) 2 pcs 14 Ball Joint, lower, (SKA 513, H1-5103, Hilux) 2 pcs 15 Ball Joint, Upper, (SKA 513, H1-5103, Hilux) 2 pcs 16 Stabilizer link, (SKA 513, H1-5103, Hilux) 2 pcs 17 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux) 2 pcs 18 Hub bearing, (SKA 513, H1-5103, Hilux) 2 pcs	
3	
4 Ball joint, upper, (L300), (B2-A069, H1-6403, L300) 5 Ball joint, lower, (L300), (B2-A069, H1-6403, L300) 6 Idler arm, (B2-A069, H1-6403, L300) 7 Center post, (B2-A069, H1-6403, L300) 8 Wheel bearing, outer, (B2-A069, H1-6403, L300) 9 Wheel bearing, inner, (B2-A069, H1-6403, L300) 10 Belt trunk, (B2-A069, H1-6403, L300) 11 pc 11 Belt, (B2-A069, H1-6403, L300) 12 Tie Rod end, (SKA 513, H1-5103, Hilux) 13 Rack end, (SKA 513, H1-5103, Hilux) 14 Ball Joint, lower, (SKA 513, H1-5103, Hilux) 15 Ball Joint, Upper, (SKA 513, H1-5103, Hilux) 16 Stabilizer link, (SKA 513, H1-5103, Hilux) 17 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux) 18 Hub bearing, (SKA 513, H1-5103, Hilux) 2 pcs 2 pcs 3 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux) 2 pcs 3 Pcs 4 Ball Joint, (SKA 513, H1-5103, Hilux) 4 Pcs 5 Pcs 6 Pcs 7 Pcs 7 Pcs 7 Pcs 7 Pcs 7 Pcs 7 Pcs 8 Pcs	
5 Ball joint, lower, (L300), (B2-A069, H1-6403, L300) 2 pcs 6 Idler arm, (B2-A069, H1-6403, L300) 1 pc 7 Center post, (B2-A069, H1-6403, L300) 1 pc 8 Wheel bearing, outer, (B2-A069, H1-6403, L300) 2 pcs 9 Wheel bearing, inner, (B2-A069, H1-6403, L300) 1 pc 10 Belt trunk, (B2-A069, H1-6403, L300) 1 pc 11 Belt, (B2-A069, H1-6403, L300) 3 pcs 12 Tie Rod end, (SKA 513, H1-5103, Hilux) 2 pcs 13 Rack end, (SKA 513, H1-5103, Hilux) 2 pcs 14 Ball Joint, lower, (SKA 513, H1-5103, Hilux) 2 pcs 15 Ball Joint, Upper, (SKA 513, H1-5103, Hilux) 2 pcs 16 Stabilizer link, (SKA 513, H1-5103, Hilux) 2 pcs 17 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux) 2 pcs 18 Hub bearing, (SKA 513, H1-5103, Hilux) 2 pcs	
7 Center post, (B2-A069, H1-6403, L300) 1 pc 8 Wheel bearing, outer, (B2-A069, H1-6403, L300) 2 pcs 9 Wheel bearing, inner, (B2-A069, H1-6403, L300) 2 pcs 10 Belt trunk, (B2-A069, H1-6403, L300) 1 pc 11 Belt, (B2-A069, H1-6403, L300) 3 pcs 12 Tie Rod end, (SKA 513, H1-5103, Hilux) 2 pcs 13 Rack end, (SKA 513, H1-5103, Hilux) 2 pcs 14 Ball Joint, lower, (SKA 513, H1-5103, Hilux) 2 pcs 15 Ball Joint, Upper, (SKA 513, H1-5103, Hilux) 2 pcs 16 Stabilizer link, (SKA 513, H1-5103, Hilux) 2 pcs 17 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux) 2 pcs 18 Hub bearing, (SKA 513, H1-5103, Hilux) 2 pcs	
7 Center post, (B2-A069, H1-6403, L300) 1 pc 8 Wheel bearing, outer, (B2-A069, H1-6403, L300) 2 pcs 9 Wheel bearing, inner, (B2-A069, H1-6403, L300) 2 pcs 10 Belt trunk, (B2-A069, H1-6403, L300) 1 pc 11 Belt, (B2-A069, H1-6403, L300) 3 pcs 12 Tie Rod end, (SKA 513, H1-5103, Hilux) 2 pcs 13 Rack end, (SKA 513, H1-5103, Hilux) 2 pcs 14 Ball Joint, lower, (SKA 513, H1-5103, Hilux) 2 pcs 15 Ball Joint, Upper, (SKA 513, H1-5103, Hilux) 2 pcs 16 Stabilizer link, (SKA 513, H1-5103, Hilux) 2 pcs 17 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux) 2 pcs 18 Hub bearing, (SKA 513, H1-5103, Hilux) 2 pcs	
8 Wheel bearing, outer, (B2-A069, H1-6403, L300) 2 pcs 9 Wheel bearing, inner, (B2-A069, H1-6403, L300) 2 pcs 10 Belt trunk, (B2-A069, H1-6403, L300) 1 pc 11 Belt, (B2-A069, H1-6403, L300) 3 pcs 12 Tie Rod end, (SKA 513, H1-5103, Hilux) 2 pcs 13 Rack end, (SKA 513, H1-5103, Hilux) 2 pcs 14 Ball Joint, lower, (SKA 513, H1-5103, Hilux) 2 pcs 15 Ball Joint, Upper, (SKA 513, H1-5103, Hilux) 2 pcs 16 Stabilizer link, (SKA 513, H1-5103, Hilux) 2 pcs 17 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux) 2 pcs 18 Hub bearing, (SKA 513, H1-5103, Hilux) 2 pcs	
9 Wheel bearing, inner, (B2-A069, H1-6403, L300) 2 pcs 10 Belt trunk, (B2-A069, H1-6403, L300) 1 pc 11 Belt, (B2-A069, H1-6403, L300) 3 pcs 12 Tie Rod end, (SKA 513, H1-5103, Hilux) 2 pcs 13 Rack end, (SKA 513, H1-5103, Hilux) 2 pcs 14 Ball Joint, lower, (SKA 513, H1-5103, Hilux) 2 pcs 15 Ball Joint, Upper, (SKA 513, H1-5103, Hilux) 2 pcs 16 Stabilizer link, (SKA 513, H1-5103, Hilux) 2 pcs 17 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux) 2 pcs 18 Hub bearing, (SKA 513, H1-5103, Hilux) 2 pcs	
10 Belt trunk, (B2-A069, H1-6403, L300) 1 pc 11 Belt, (B2-A069, H1-6403, L300) 3 pcs 12 Tie Rod end, (SKA 513, H1-5103, Hilux) 2 pcs 13 Rack end, (SKA 513, H1-5103, Hilux) 2 pcs 14 Ball Joint, lower, (SKA 513, H1-5103, Hilux) 2 pcs 15 Ball Joint, Upper, (SKA 513, H1-5103, Hilux) 2 pcs 16 Stabilizer link, (SKA 513, H1-5103, Hilux) 2 pcs 17 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux) 2 pcs 18 Hub bearing, (SKA 513, H1-5103, Hilux) 2 pcs	
11 Belt, (B2-A069, H1-6403, L300) 3 pcs 12 Tie Rod end, (SKA 513, H1-5103, Hilux) 2 pcs 13 Rack end, (SKA 513, H1-5103, Hilux) 2 pcs 14 Ball Joint, lower, (SKA 513, H1-5103, Hilux) 2 pcs 15 Ball Joint, Upper, (SKA 513, H1-5103, Hilux) 2 pcs 16 Stabilizer link, (SKA 513, H1-5103, Hilux) 2 pcs 17 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux) 2 pcs 18 Hub bearing, (SKA 513, H1-5103, Hilux) 2 pcs	
13 Rack end, (SKA 513, H1-5103, Hilux) 2 pcs 14 Ball Joint, lower, (SKA 513, H1-5103, Hilux) 2 pcs 15 Ball Joint, Upper, (SKA 513, H1-5103, Hilux) 2 pcs 16 Stabilizer link, (SKA 513, H1-5103, Hilux) 2 pcs 17 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux) 2 pcs 18 Hub bearing, (SKA 513, H1-5103, Hilux) 2 pcs	
13 Rack end, (SKA 513, H1-5103, Hilux) 2 pcs 14 Ball Joint, lower, (SKA 513, H1-5103, Hilux) 2 pcs 15 Ball Joint, Upper, (SKA 513, H1-5103, Hilux) 2 pcs 16 Stabilizer link, (SKA 513, H1-5103, Hilux) 2 pcs 17 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux) 2 pcs 18 Hub bearing, (SKA 513, H1-5103, Hilux) 2 pcs	
15 Ball Joint, Upper, (SKA 513, H1-5103, Hilux) 2 pcs 16 Stabilizer link, (SKA 513, H1-5103, Hilux) 2 pcs 17 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux) 2 pcs 18 Hub bearing, (SKA 513, H1-5103, Hilux) 2 pcs	
15 Ball Joint, Upper, (SKA 513, H1-5103, Hilux) 2 pcs 16 Stabilizer link, (SKA 513, H1-5103, Hilux) 2 pcs 17 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux) 2 pcs 18 Hub bearing, (SKA 513, H1-5103, Hilux) 2 pcs	
17 Stabilizer bar bushing, (SKA 513, H1-5103, Hilux) 2 pcs 18 Hub bearing, (SKA 513, H1-5103, Hilux) 2 pcs	
18 Hub bearing, (SKA 513, H1-5103, Hilux) 2 pcs	
19 Transmission support, (SKA 513, H1-5103, Hilux) 1 pc	
Labor	
OTAL AMOUNT IN WORDS	
Frand and Model : Warranty : Price Validity :	