

Page 1 of 1

Republic of the Philippines DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS

NEGROS OCCIDENTAL 1ST DISTRICT ENGINEERING OFFICE

Region VI

		Matab-ang,	Talisay City					
Name of Procuring Entity		: DPWH Negros Occidental 1st DEO	PR No. / Quotation	No.:	24-03-0025	5 / 03	-2024-008 SP	
Revised On		:	1	Date : M	arch 20, 2024			
Standard Form/Title		: REQUEST FOR QUOTATION	Office/End-	Office/End-User : Mair		tenance Section		
COM	PANY NAME	:		_				
ADDI	RESS	:						
TEL.	NO./FAX No.	:		TIN:			_	
	Please quote your lo	owest price on the item(s) listed below, sub	ject to the Terms and (Conditio	ns stated belo	w and p	ersonally submit	
your o	quotation duly signed	by your representative not later than 8:30	A.M. of March 2	7, 2024	in the	return e	nvelope attached	
herew	vith, to the BAC Secre	etariat for Goods, DPWH Negros Occidental	1st DEO, Matab-ang, T	alisay Ci	ty, Negros Od	ccidental		
TERM	S and CONDITIONS:							
	entries must be typewrit			į				
		v-Five (<u>45</u>) C.D. upon receipt of the approved fu Irsuant to Sec.69 of the Revised IRR-RA 9184 sha						
without valid reason.						411		
		nimum of three (3) months for supplies & materials; one (1) year for Equipment; date of acceptance by the end-user.				80r		
		period of sixty (60) calendar days.				EVANGELINE N. LIMOS		
		ficate, Mayor's Permit and Omnibus Sworn Statement shall be attached				Engineer III		
,	on submission of the qua ders shall submit origina	otation. al brochures of the product.		j	BA	AC Chairp	person	
		or each items being offered.	,110.00	į				
8. Inc	e approvea buaget ceilin	ng for this procurement is P 107	<u>,110.00</u>					
ITEM NO.		ITEM AND DESCRIPTION	QТ	Y. UN	IIT UNIT	PRICE	TOTAL PRICE	
		. Plates Code:574H28L (12V 74AH)						
2	Toyota Innova NCJ 9 Aircon Belt		ruck					
	Fan Belt	Hino 300s Mini Dumpt H3-6843/JM 8511/YM						
4	Hub Bolt Right Rear	Isuzu Dump Tr	uck					
	Hub Bolt Left Rear	SCR 979/H3-46	513					
	Wheel cylinder (Fron Water Pump Repair I							
	Copper Tube 5/16							
	Radiator Hose Upper							
	Bolt and Hut w/ Was Acetylene	sher 10mmx1"						
	Oxygen							
13	Bronze Rod							
	Center Bearing	Toyota Hilux ABA 3137/H1-8927/YM 201 Front, Left & Right) Toyota Innova FAB 7						
	Round File (3/8Ø")	Motorpool	779/11/12010				1	
17	Triangular File (3/8")							
	Half Round File (1/2' Flat File (1/2")	")						
	Sander Blade							
21	Sander Stone Blade (
22	Welding Rod (60/13)							
	<i>x-x-x-x-x-x-x-x-x-x-x-x-x-x-x-x-x-x-x-</i>	-X-X-X-X						
	All Items are Replacem	nent						
		arts for use of Various Vehicle whose						
_		in line to their Item, assigned in Va ngineering Office, Matab-ang, Talisay (-	_	os TO	TAL		
	d & Model	·	Warra		I		<u>I</u>	
	ery Period		Price Vali	· –				
	-	·		_	to above If the	0 cpace 4	or Dolivory Poriod	
		nd accepted your General Conditions, I/We quot e left blank, it means that I concur with the Term				= space r	or Delivery Period,	
				_				
DPWH-	G&S-42				Printed I	Name/Sig	nature/Date	
M098 S	P			-	Tol No / C	ollphono	No / E-Mail Add	
Dane 1	of 1				161. NO. / C	enhuone i	No. / E-Mail Add	