

DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS Republic of the Philippines

OFFICE OF I SECRETARY

Manila

June 28, 2018

MEMORANDUM

MARK A. VILLAR

Secretary

This Department

This refers to the memorandum dated 25 June 2018 of **DPWH Region III Director ANTONIO V. MOLANO, JR.**, endorsing their request for approval of Modification of the project under FY 2018 General Appropriations Act., (GAA), to wit:

					Justification:	_
₽1.00B		Total	₽1.00B	_	Total	
₽29.10M		EAO	₽35.00M		EAO	
₽140.00M	₽300 /sq.m.	ROW (ROW Acquisition)/				
₽103.171M	₽271.503/ lm	CW-2 (Construction of Prainage Structure along Road)/ 380.00 lm	₽289.50M	₽85,393.19/ sq.m.	CW-2 (Construction of Concrete Bridge)/ 3,390.20 sq.m.	
₽727.729M	₽13.231M ✓ /ln-km	CW-1 (Construction of Gravel Road)/ 55.000 In-km	₽675.50M	P10.555M/ In-km	CW-1 (Construction of Concrete Road)/ 64.000 ln-km	
Estimated Cost	Unit Cost	Type of Work / Physical Target	Allocation in P '000	Unit Cost	Type of Work / Physical Target	
Lubao-Guagua-	nt/Upgrading of l	Construction/Improvement/Upgrading of Lubao-Guagua-Minalin-Sto. Tomas Road, Pampanga	Lubao-Guagua-	ment/Upgrading of pad, Pampanga	Construction/Improvement/Upgrading of Lubao-Guagua-Minalin-Sto. Tomas Road, Pampanga	
jes - Local n/Improvement rojects	Roads and Bridg pair/Rehabilitation including Local P	LOCAL PROGRAM - Local Roads and Bridges - Local Roads - Construction/Repair/Rehabilitation/Improvement of Various Infrastructure including Local Projects	ges - Local n/Improvement ⁹ rojects	cal Roads and Brid Repair/Rehabilitatio Ire including Local I	LOCAL PROGRAM - Local Roads and Bridges - Local Roads - Construction/Repair/Rehabilitation/Improvement of Various Infrastructure including Local Projects	
				00002000 764LZ	UACS No. 300116200002000 Project ID: P00257764LZ	
		escription	Project Description			
	As Modified	As		As per GAA/Original	Asp	

- The modification is hereby sought due to the following reasons;

 1. CW1 "Construction of Concrete Road" changed to "Construction of Gravel Road" since the project is a road opening. The existing road foundation is not yet suitable/capable to support Portland Cement Concrete Pavement opening.
- 2 Unit cost for CW1 increased due to the additional quantities for ITEM 104(2)a – Embankment from borrow (Common Soil), ITEM 608(1) – Furnishing and Placing Top Soil, ITEM 610(1) – Sodding, ITEM 715(1)b –
- ω Separation Geotextile which constitute 68.06%, 4.45%, 4.32% and 9.32% of the total direct cost respectively. CW2 – "Construction of Concrete Bridge" changed to "Construction of Drainage Structure along Road" since the proposed construction of bridges will require additional feasibility studies on the highway drainage especially on the proposed viaducts. Program of Work includes construction of Reinforced Concrete Box Culverts with a total length of 380 l.mx
- ROW is added in order to acquire affected agricultural lands

hereof is recommended. Based on our evaluation, the submitted request for modification of the said project is in order, hence, approval

Undersecretary for Regional Operations Regions I, IJ III, IV-A, V& CAR APPROVED/DISAPPROVED:

DIMAS S

SQUILON

Secretary MARK A. VILLAR

Department of Public Works and Highways
Office of the Secretary WIN8G02500