



Repair/Maintenance of DPWH Building Zamboanga City 2nd DEO Bldg. Administrative Building (Construction Section) Phase II, MCLL Highway, Divisoria, Zamboanga City.

25/01/2019

FORM POW-2015-01B-00

MINIMUM EQUIPMENT REQUIREMENT

No.	Equipment Description	Capacity	Number of Equipment	No.	Labor Description		Number of Labor
1	One Bagger Mixer		1	1	Construction Foreman		1
2	Bar Cutter		1	2	Safety Officer		1
3	Bar Bender		1	3	Skilled Laborer		2
4	Stake Truck		1	4	Laborers		10
5				5			
6				6			
7				7			
8				8			
9				9			
10				10			
11				11			
12				12			
13				13			
14				14			
15				15			
16				16			
17				17			
18				18			
19				19			
20				20			
21				21			
22				22			
23				23			
24				24			
25				25			
26				26			
27				27			
28				28			
29				29			
30				30			
	SUB-TOTAL		4		SUB-TOTAL		14
TOTAL							18