



Republic of the Philippines
DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS
Sultan Kudarat 1st District Engineering Office
Isulan, Sultan Kudarat, Region XII

Name of Procuring Entity : SK 1st District Engineering office Request For Quotation : 2024-08-0035 (P.R. No.) 2024-07-0048

Revised on : Date : August 7, 2024

Standard Form/Title : REQUEST FOR QUOTATION Office/End-User : SK 1ST DEO

COMPANY NAME :

ADDRESS :

TEL. NO./FAX No. :

Please quote your lowest price on the item(s) listed below, subject to the Terms and Conditions stated below and submit your quotation duly signed by your representative not later than 10:00 A.M. of AUG 16 2024 in the return envelope attached herewith, to the Goods & Services Division, Procurement Services, 5th Floor, Bonifacio Drive, Port Area, Manila.

TERMS and CONDITIONS :

1. All entries must be typewritten or legibly written.
2. Delivery period within 30 Calendar Days upon receipt of the approved funded Purchase Order (P.O). Administrative penalties pursuant to Sec. 69 of the Revised IRR-RA 9184 shall be imposed for non-delivery without valid reason.
3. Warranty shall be for a minimum of three (3) months for supplies & materials; one year for Equipment; 3 years IT Equipment from date of acceptance by the end-user.
4. Price validity shall be for a period of sixty (60) calendar days.
5. G-EPIS Registration Certificate/Mayor's Permit/DTI shall be attached upon submission of the quotation.
6. Bidders shall submit original brochures of the product.
7. Please indicate the brand for each items being offered.
8. The approved budget ceiling for this procurement is Php 407,635.31

RAUL N. TRAVILLA
BAC - Chairman

Item No.	ITEMS & DESCRIPTION	QTY.	UNIT	UNIT PRICE	TOTAL PRICE
Purchase of Vehicle Parts and Accessories for use of Various Service Vehicles in the SK 1st DEO for the 3rd Quarter CY 2024					
	P1-H991 (H1-7468) TOYOTA HILUX 2.8L MT 2019 Engine: 1GD-4661987, Chassis: MROH1BCD5K1093612				
1	Tire 265/65 R17 AT	4	pcs		
2	Oil Filter Toyota 90915-YZZD2	2	pcs		
3	Fuel Filter Toyota 23390-0L070	2	pcs		
4	Aircon Cabin Filter - Genuine	1	pc		
5	Brake Pad - Genuine	1	set		
6	Air Cleaner - Genuine	1	pc		
7	Rain Visor	1	set		
	SJP-653 (H1-5569) HILUX 2009 Engine: 1KD-787513, Chassis: MRDF29G002515341				
8	Oil Filter Toyota 90915-YZZD2	2	pcs		
9	Fuel Filter Toyota 23390-0L041	2	pcs		
10	Air Cabin Filter - Genuine	2	pcs		
11	Shock Absorber Rear (Left an Right)	1	set		
12	Shock Absorber Front (Left an Right)	1	set		
13	Fuel Injector	4	sets		
	SGX-354 (H1-5568) ISUZU FUEGO 4X4 1998 Engine: 4JB1-231097, Chassis: JAATFS55HT9101711				
14	Oil Filter C-512	2	pcs		
15	Fuel Filter FC-208A	2	pcs		
16	Batter 12V, 11Plates	1	pc		
17	Tie Rod End	1	set		
	SAA-5008 (H1-7615) TOYOTA HILUX 4X4 3.0L MT 2015 Engine: 1KD-U756401, Chassis: MR0FZ29G602578427				
18	Ball Joint (Lower) Left and Right	1	set		
19	Aircon Cabin Filter	3	pcs		
20	Rain Visor	1	set		
21	Windshiled Tint, nano ceramic	1	set		
22	CV Joint Rubber Boots	1	set		

Brand and Model : _____ Warranty : _____
Delivery Period : _____ Price Validity : _____

After having carefully read and accepted your General Conditions, I / We quote you on the item(s) at prices note above. If the space for Delivery Period, Warranty and Price Validity are left blank, it means that I concur with the Terms and Conditions specified by DPWH.

Republic of the Philippines
DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS
Sultan Kudarat 1st District Engineering Office
Isulan, Sultan Kudarat, Region XII